

Fig. 1




Fig. 2




Fig. 3




Fig.4

CALL OUT LIST OF ELEMENTS

- 100 Microdermabrasion machine
- 105 Vacuum
- 205 Supply Canister
- 5 210 Storage Canister
- 215 Canister Tops
- 220 Supply Canister Bore
- 225 Canister Bottom
- 230 Canister Rack
- 10 235 Canister Rack Bore
- 240 Canister Cavity
- 250 First Storage Canister Tube
- 255 Storage Canister Bore
- 260 Second Storage Canister Tube
- 15 305 Conduits
- 310 Storage Canister Filter
- 315 Air Inlet
- 320 Supply Canister Filter
- 325 Feeding Conduit
- 20 330 O-ring
- 350 Horizontal Locking Pin
- 360 Vertical Locking Pin
- 370 Latches
- 405 New Abrasive Crystals
- 25 410 Used Abrasive Crystals